



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210  
PO Box 145801  
Salt Lake City, Utah 84114-5801  
(801) 538-5340 telephone  
(801) 359-3940 fax  
(801) 538-7223 TTY  
www.nr.utah.gov

Michael O. Leavitt  
Governor  
Robert L. Morgan  
Executive Director  
Lowell P. Braxton  
Division Director

October 8, 2002

TO: Minerals File

FROM: Tom Munson, Senior Reclamation Hydrologist *RM*

RE: Site Inspection, Torrey (AM Stone 110&101) Quarry, Star Stone Quarries, Inc., S/055/016, Wayne County, Utah

Date of Inspection: September 20, 2002  
Time of Inspection: 10:00 a.m.-12 Noon  
Conditions: Sunny  
Participants: Tom Munson, Senior Reclamation Specialist - DOGM

**Purpose of Inspection:** To perform an annual inspection of the project area.

**Observations:**

When I arrived onsite, it was noted that the site had been recently active; there was an assortment of trailers and mining/processing equipment that had been left on site. There was also a variety of palletted stone products on the site. I performed a GPS survey of the disturbances and determined the disturbed area to be in excess of five acres. Please refer to the attached GPS map and pictures documenting the mine site conditions at that time.

I found two areas of mining-related disturbance. The first area shown as 0.24 acres on the attached map was scraped clean of soil and was solid sandstone. Piles of salvaged soil material were stockpiled around the perimeter of this site disturbance. There was a short road approximately 542 feet long and 12 feet wide joining the adjacent 6.56 acre disturbance. The main disturbance consisted of a palletted stone stockpile area and associated mine excavations. Equipment found on site consisted of a trailer, a fuel truck, a water truck, a loader and a stone saw.

**Conclusions and Recommendations:**


This overall site disturbance has been expanded to a large mine operational status. As such, the mining should be suspended until a transitional surety is filed with the Division and the disturbed area boundaries are physically marked. A large mine permit application should also be completed and filed with the Division as soon as possible.

jb

Attachments: GPS map & photos  
O:\M055-Wayne\s0550016-TorreySandstone\final\insp-09202002.doc




# Torrey(AM Stone 100 & 101) M/055/016



800 0 800 1600 2400 Feet

Location: Section 8, S 1/2,  
T 28 S, R4 E, USGS Quad-Torrey, Utah  
Inspection Date: September 20, 2002



This product may not meet DOGM standards for accuracy and content. Different data sources and input scales may cause some misalignment of data layers.